

**Appendix 1**

**Site Red Line Boundary – Romney Close**



**Site Red line boundary – Mount View Court**



## Appendix 2

### Romney Close survey of the existing and proposed boundary fencing

#### 9.0 Existing Survey and Proposed Strategy for Boundary Fencing:

Visual Survey of Fence Types + Condition

The proposed strategy is to fully re-secure the boundary fencing by repairing and restoring all fencing types, and replacing or installing new panels locally where necessary or stated. The timber fencing (1-2) should also be power washed and re-stained. The restored fencing will be further reinforced by the hedgerow, as a living wall.

