


FABRIC REPAIRS – EXTERNAL ELEVATIONS – 2015/16 APPENDIX 1



Brick, render & glazing repairs to SE Tower

Alexandra Palace, United Kingdom
Directions Save Zoom Send

Brick & render repairs to south elevation of GH

Brick & render repairs to South Basement/Traitor's Gate

Parapet & interim repairs to E & W colonnade bays

Pigeon guano removal internally to SW Tower

Interim repairs to south face of North Wall

Essential drainage, investigation & ventilation to Area 1 (under PR)

Brick & render repairs to north elevation of GH

Interim repairs to north face of North Wall

Elevation & roof maintenance to Service Yard buildings

Joinery repairs & redecoration to LR, PC and B&K